Pikes Peak (Colorado) 2023 UA Compliance



Property 10226 Hartwood Dr Peyton, CO 80831 Model: 5291

Community: Paint Brush Hills

10226 Hartwood Dr Meritage Homes Partial Crawlspace - with Inspection Data **Organization** EnergyLogic

Justin Alletto

Inspection Status 2025-08-06 Rater ID (RTIN): 2151087 RESNET Registered (Confirmed)

Builder Meritage Homes

Building UA

Elements	IECC Reference	As Designed
Ceilings	47.1	47.9
Above-Grade Walls	176.2	163.3
Windows, Doors and Skylights	115.2	102.5
Slab Floor:	32.1	32.1
Framed Floors	12.5	12.2
Foundation Walls	60.0	46.3
Rim Joists	13.5	11.7
Overall UA (Design must be equal or lower):	456.6	416.0

Requirements

	R402.1.5	Total UA alternative compliance passes by 8.9%.	The proposed home meets the UA requirement by 8.9%
	R402.3.2	Glazed Fenestration SHGC	
1	R402.2.9	Slab insulation is evaluated through total UA.	
	R402.4.1.2	Air Leakage Testing	Air sealing is 1.20 ACH at 50 Pa and 0.11 CFM50 / ${\rm ft}^2$ Shell Area. It must not exceed 5.00 ACH at 50 Pa or 0.28 CFM50 / ${\rm ft}^2$ Shell Area.
	R403.3.1	Duct Insulation	All ducts are inside the thermal envelope or outside and insulated to at least R8.0.
	R403.3.5	Duct Testing	
	R403.6	Mechanical Ventilation	
	R404.1	Lighting Equipment	
	Mandatory Checklist	Mandatory code requirements that are not checked by Ekotrope must be met.	2021 IECC Required Items must be checked as complete.
	R403.6.2	Mechanical Ventilation Efficacy	
	R403.6.1	Mechanical Ventilation Energy Recovery	

Design exceeds requirements for Pikes Peak (Colorado) 2023 Prescriptive compliance by 8.9%.

Name:	Justin Alletto	Signature:	/ was / (Namo	
Organization:	EnergyLogic	Digitally signed:	8/6/25 at 4:17 PM	

10226 Hartwood Dr

Peyton, CO 80831

Builder: Meritage Homes

Model: 5291 Community: Paint Brush Hills

THIS HOME IS CERTIFIED TO MEET THE PIKES PEAK (COLORADO) 2023 ENERGY CODE

Building Features

Ceiling Vaulted Roof, R-38

Duct Supply R-0.0, Return R-0.0

Above Grade Walls R-20 **Duct Leakage to Outside** Untested Forced Air

Foundation Walls R-19 Total Duct Leakage 152 CFM @ 25Pa (Rough-In, with Air Handler)

Framed Floor R-30 Heating Furnace • Natural Gas • 96.7 AFUE

Slab R-0.0 Perimeter, R-0.0 Under **Cooling** Air Conditioner • Electric • 13.4 SEER2

Infiltration 908.3 CFM50 (1.20 ACH50) Water Heating Residential Water Heater • Electric • 0.92 UEF

Window U-Value: 0.3, SHGC: 0.36

As a 3rd party extension of the code jurisdiction utilizing these reports, I certify that this energy code compliance document has been created in accordance with the requirements of Chapter 4 of the adopted International Energy Conservation Code based on EL PASO County. If rating is Projected, I certify that the building design described herein is consistent with the building plans, specifications, and other calculations submitted with the permit application. If rating is Confirmed, I certify that the address referenced above has been inspected/tested and that the mandatory provisions of the IECC have been installed to meet or exceed the intent of the IECC or will be verified as such by another party.

Ekotrope RATER - Version 4.2.3.3684

Pikes Peak (Colorado) 2023 Certificate compliance results calculated using Ekotrope RATER's energy and code compliance algorithm, including appropriate amendments.

Ekotrope RATER is a RESNET Accredited HERS Rating Tool. All results are based on data entered by Ekotrope users.

Ekotrope disclaims all liability for the information shown on this report.

Pikes Peak (Colorado) 2023 Label

10226 Hartwood Dr

Model: 5291

Ekotrope RATER - Version: 4.2.3.3684

HERS® Index Score: 55

Building Envelope Specs

Ceiling: R-38

Above Grade Walls: R-20 Foundation Walls: R-19 Exposed Floor: R-30

Slab: R-0

Infiltration: 908.3 CFM50 (1.20 ACH50) Duct Insulation: Supply: R0, Return: R0 Duct Lkg to Outdoors: Untested Forced Air

Window & Door Specs

U-Value: 0.3, SHGC: 0.36

Door: R-5

Mechanical Equipment Specs

Heating: Furnace • Natural Gas • 96.7 AFUE
Cooling: Air Conditioner • Electric • 13.4 SEER2

Hot Water: Residential Water Heater • Electric • 0.92 UEF

Average Mechanical Ventilation: 89 CFM

Builder or Design Professional

Signature:

Air Leakage Report

Property

10226 Hartwood Dr Peyton, CO 80831 Model: 5291

Community: Paint Brush Hills

Model: 5291

10226 Hartwood Dr Meritage Homes Partial Crawlspace - with Inspection Data Organization

EnergyLogic

Justin Alletto

Builder

Meritage Homes

Inspection Status

2025-08-06

Rater ID (RTIN): 2151087

RESNET Registered

(Confirmed)



General Information

Conditioned Floor Area [ft²]	4,160
Infiltration Volume [ft³]	45,506
Number of Bedrooms	5

Air Leakage

Measured Infiltration	908.3 CFM50 (1.20 ACH50)
ACH50 (Calculated)	1.20
ELA [sq. in.] (Calculated)	49.83
ELA per 100 s.f. Shell Area (Calculated)	0.600
CFM50 (Calculated)	908
CFM50 / s.f. Shell Area (Calculated)	0.109

Duct Leakage

	System 1
Leakage to Outdoors	Untested Forced Air
Estimated Leakage to Outside	76 CFM25
Total Leakage Test Type	Rough-In, with Air Handler
Total Leakage [CFM @ 25 Pa]	152.0
Total Leakage [CFM25 / 100 s.f.]	3.7
Total Leakage [CFM25 / CFA]	0.037

Mechanical Ventilation

Rate [CFM]	89 CFM
Hours per day	24.0
Fan Power	15 Watts
Recovery Efficiency %	0.0
Runs at least once every 3 hrs?	true
Average Rate [CFM]	89.0 CFM
2010 ASHRAE 62.2 Req. Cont. Ventilation	86.6
2013 ASHRAE 62.2 Req. Cont. Ventilation	124.2
2016 ASHRAE 62.2 Req. Cont. Ventilation	157.6

Property 10226 Hartwood Dr Peyton, CO 80831 Model: 5291 Community: Paint Brush Hills

10226 Hartwood Dr Meritage Homes Partial Crawlspace - with Inspection Data Organization EnergyLogic Justin Alletto

Builder Meritage Homes Inspection Status 2025-08-06 Rater ID (RTIN): 2151087 RESNET Registered (Confirmed)



General Building Information		
Number Of Bedrooms: 5	Number Of Floors: 2	
Conditioned Floor Area [sq. ft.]: 4,160	Has Electric Vehicle Ready Space: No	
Unconditioned, attached garage? Yes	Conditioned Volume [cu. ft.]: 45,506	
Total Units in Building: 1	Residence Type: Single family detached	
Number of Floors in Building: N/A	Floor Number: N/A	
Model: 5291	Community: Paint Brush Hills	
RESNET/IECC 2006-2018 Climate Zone: 5B	IECC 2021 Climate Zone: 5B	

Foundation Wal	I					
Name	Library Type	Height Above Grade	Depth Below Grade	Perimete	r Location	n Enclosing
Ambient	R19 Draped Full	1	7	94	Exposed Exterior	Conditioned Space
Crawl	R19 Draped Full	1	3	31	Exposed Exterior	Conditioned Crawlspace
Garage	R19 Draped Full	1	7	43	Exposed Exterior	Conditioned Space

Envelope Components

Foundation Wall Library List								
Name Feet From Wall Top To Feet Continuous Insulation Cont Top		Feet From Wall Top To Continuous Insulation Bottom	,	Continuous R-value	Cavity R-value	Effective Insulation R- value		
R19 Draped Full	N/A	N/A	Yes	19.00	N/A	N/A		

Slab								
Name	Library Type	Perimeter	Floor Grade	Carpet R	Exposed Masonry Area		Location	n Enclosing
Basement	Uninsulated Slab	124	Below Grade	0	1,104	1,104.0 ft²	Exposed Exterior	Conditioned Space
Crawlspace	Uninsulated Slab	44	Below Grade	0	234	234.0 ft²	Exposed Exterior	Conditioned Crawlspace

Slab Librai	ry List							
Na	me Wall Construction Type	Slab Completely Insulated?	Underslab Insulation Width [t]	Perimeter Insulation Depth [t]	Perimeter Insulation R Value		Thermal Break	Effective R-value
Uninsulated Si	ab Wood Frame / Other	No	0	0	0	Yes	No	0.00

Framed Floor									
Name	Library Type	Carpet R	Floor Grade	Surface Area	Location	Effective R-value			
Over Garage	12" R30 OCF 19.2" OC	1	Above Grade	380.0 ft²	Unconditioned, attached garage	31.256			

Rim Joist									
Name	Library Type	Surface Area	Location	Effective Insulation R-value					
Ambient	R 20	250.0 ft²	Exposed Exterior	20.00					
Garage	R 20	43.0 ft²	Unconditioned, attached garage	20.00					

Property 10226 Hartwood Dr Peyton, CO 80831 Model: 5291 Community: Paint Brush Hills Project & Plan 10226 Hartwood Dr Meritage Homes Partial Crawlspace - with Inspection Data Organization EnergyLogic Justin Alletto Inspection Status 2025-08-06 Rater ID (RTIN): 215108 Builder Meritage Homes

Wall									
Name	Library Type	Surface Colo	r Solar Absorptance	Surface Area	Location	Effective R-value			
All 2x6 exterior walls	2x6 R20 16" OC OCF	Medium	0.75	2,878.0 ft²	Exposed Exterior	17.986			
Garage 2x6	2x6 R20 16" OC OCF	Medium	0.75	387.0 ft²	Unconditioned, attached garage	17.986			

Glazing									
Name	Library Type	Wall Assignment	Foundation Wall Assignment	is Operable	Overhang Depth		Overhang Ft To Bottom	Orientation	Surface Area
Back 2x6	3036	All 2x6 exterior walls		Yes	0	0	0	West	130.0 ft²
Back Sider 2x6	2840	All 2x6 exterior walls		Yes	0	0	0	West	48.0 ft²
Back bsmt	2923		Ambient	Yes	0	0	0	West	32.0 ft ²
Front 2x6	3036	All 2x6 exterior walls		Yes	0	0	0	East	81.0 ft²
Left 2x6	3036	All 2x6 exterior walls		Yes	0	0	0	South	21.0 ft²
Right 2x6	3036	All 2x6 exterior walls		Yes	0	0	0	North	6.0 ft²

Glazing Library List

Name	Shgc	U-factor		
2840	0.4	0.280		
2923	0.23	0.290		
3036	0.36	0.300		

Opaque Do	Dpaque Door											
Name	Library Type	Wall Assignment	Foundation Wall Assignment	Emittance	Solar Absorptance		Surface Area	Location	Effective R- value			
Front 2x6	R 5; U-value 0.20	All 2x6 exterior walls		0.9	0.75	Medium	21.0 ft ² Ex	xposed Exterior	5.00			
Garage x6	R 5; U-value 0.20	Garage 2x6		0.9	0.75	Medium		Unconditioned, attached garage	5.00			

Roof Insula	Roof Insulation										
Nam	e Library Type	Attic Exterior Area [ft²]					Solar Absorptance	Surface Area	Location		
Vault OPEN	R-38 OCF 24"oc roof	1,810	No	No	-	Medium	0.75	1,810.0 ft²	Vaulted Roof		

Roof Insulation Library List			Whole House In	Whole House Infiltration			
Name	Has Radiant Barrier	Effective R-value	Infiltration	Measurement Type	Shelter Class		
R-38 OCF 24"oc roof	No	37.811	908.3 CFM at 50 Pa	Blower-door tested	4		

Mechanicals, Lights & Water

Property 10226 Hartwood Dr Peyton, CO 80831 Model: 5291 Community: Paint Brush Project & Plan 10226 Hartwood Dr Meritage Homes Partial Crawlspace - with Inspection Data

Organization EnergyLogic Justin Alletto Inspection Status 2025-08-06 Rater ID (RTIN): 215108 Builder Meritage Homes

1/	O	F 18/-44-	D	F	
Mechanical Ventilation					
Community: Paint Brush Hills					

Ventilation Type	Ventilation Rate [ft ^a / Minute]	Operational hours per day	Fan Watts	Runs once every three hours		Model Number	Manufacturei
Exhaust Only	89 CFM	24	15 Watts	Yes	0		

Lighting					
% Interior Fluorescent Lighting		% Exterior Fluorescent Lighting		% Garage Fluorescent Lighting	% Garage LED Lighting
0	100	0	100	0	100

Conditioning Equipment										
Name	Library Type	Serial Number	Heating Percent Load	Cooling Percent Load	Hot Water Percent Load	Location				
Air conditioner (3)	13.4SEER2/48BTU 4 Ton		0%	100%	0%	Conditioned Space				
Fuel-fired air distribution (1)	59TP6C080V2120		100%	0%	0%	Conditioned Space				
Water Heating (2)	ENT-50 130		0%	0%	100%	Conditioned Space				

Equipment Type: 13.4SEER2/48BTU 4 Ton		
Equipment Type	Air Conditioner	
Fuel Type	Electric	
Distribution Type	Forced Air	
Motor Type	ECM (Variable Speed)	
Heat Pump System Type	Unspecified	
Cooling Efficiency	13.4 SEER2	
Cooling Capacity [kBtu/h]	48	

Equipment Type: 59TP6C080V2120			
Equipment Type	Furnace		
Fuel Type	Natural Gas		
Distribution Type	Forced Air		
Motor Type	ECM (Variable Speed)		
Heating Efficiency	96.7 AFUE		
Heating Capacity [kBtu/h]	78		
Use default EAE	No		
EAE [kWh]	360		

Equipment Type: ENT-50 130		
Equipment Type	Residential Water Heater	
Fuel Type	Electric	
Distribution Type	Hydronic Delivery (Radiant)	
Hot Water Efficiency	0.92 UEF	
Tank Capacity (gal.)	50	
Hot Water Capacity [kBtu/h]	15.4	
Recovery Efficiency	0.98	

Distribution System	
Distribution Type	Forced Air
Heating Equipment	Fuel-fired air distribution (1)
Cooling Equipment	Air conditioner (3)
Sq. Feet Served	4,160
# Return Grilles	5
Supply Duct R Value	0
Return Duct R Value	0
Supply Duct Area [ft²]	1123.2
Return Duct Area [ft²]	1040
Leakage to Outdoors	Untested Forced Air
Estimated LtO	76.00 CFM25
Total Leakage	152 CFM25
Total Leakage Duct Test Conditions	Rough-In, with Air Handler
Use Default Flow Rate	Yes
Duct 1	
Duct Location	Conditioned Space
Percent Supply Area	100
Percent Return Area	100

Property 10226 Hartwood Dr Peyton, CO 80831 Model: 5291 Community: Paint Brush Hills Project & Plan 10226 Hartwood Dr Meritage Homes Partial Crawlspace - with Inspection Data Organization EnergyLogic Justin Alletto Inspection Status 2025-08-06 Rater ID (RTIN): 215108 Builder Meritage Homes

Water Distribution	
Water Fixture Type	Low-flow
Use Default Hot Water Pipe Length	No
Hot Water Pipe Length [ft]	60
At Least R3 Pipe Insulation?	Yes
Hot Water Recirculation System?	No
Drain Water Heat Recovery?	No

Appliances & Notes

Clothes Dryer	
Cef	3.01
Fuel Type	Electric
Field Utilization	Timer Controls
Is Outside Conditioned Space	No
Defaults Type	HERS Reference
Is Ventless	No
Is Heat Pump	No
Clothes Dryer Available	Yes

Clothes Washer	
Label Energy Rating	400 kWh/Year
Annual Gas Cost	\$27.00
Electric Rate	\$0.12/kWh
Gas Rate	\$1.09/Therm
Capacity	3
Imef	1
Defaults Type	HERS Reference
Load Type	Front-load
Loads Per Week	6
Is Outside Conditioned Space	No
Clothes Washer Available	Yes

Dishwasher	
Dishwasher Defaults Type	Custom
Dishwasher Size	Standard
Dishwasher Efficiency	240 kWh
Annual Gas Cost	\$33.12
Electric Rate	\$0.12/kWh
Gas Rate	\$1.09/Therm
Is Outside Conditioned Space	No
Dishwasher Available	Yes

Appliances and Controls	
Programmable thermostat?	Yes
Range/Oven Fuel	Natural Gas
Convection Oven?	No
Induction Range?	No
Range/Oven Outside Conditioned Space?	No
Refrigerator Consumption	640 kWh/Year
Refrigerator Outside Conditioned Space?	No

Components Not Found: Skylight, Onsite Generation, Solar Generation, Dehumidifier, Whole House Fan, Whole House Fan Library List, HVAC Grading (Not Conducted), Ceiling Fan, Notes

Final Inspection Report



Prepared for: Meritage Homes

10226 Hartwood Dr Peyton, CO 80831

Supervisor: Michael Fischer Subdivision: Paint Brush Hills

Plan name: 5291

Inspection performed by: Justin Alletto (RTIN: 2151087)

Justo Alletto

Inspected for the following programs/codes:

- Energy Star
- IAP
- PPRBC 2023 IECC Compliance

Inspection Results: Passed

Inspection History			
Inspection	Rater	Result	
Final Inspection	Justin Alletto	/	
Insulation & Air Barrier Inspection	Kevin Coleman - RFI	/	
Duct Leakage Inspection	Kevin Coleman - RFI	~	
	Kevin Coleman - RFI		
	Inspection Final Inspection Insulation & Air Barrier Inspection	InspectionRaterFinal InspectionJustin AllettoInsulation & Air Barrier InspectionKevin Coleman - RFIDuct Leakage InspectionKevin Coleman - RFI	

If you have any questions about this report, do not hesitate to contact me directly. **Justin Alletto**, justin.alletto@nrglogic.com, 720-818-3770





10226 Hartwood Dr

Local Mechanical Exhaust

Bath Fans: exhaust more than 50 CFM intermittent or 20 **Inspection item:**

CFM continuous.

Result:

Job ID: 113917



Inspection log:

8/6/2025

Action needed: All fans passed ventilation requirements

Note from rater:

10226 Hartwood Dr

Building Shell/Blower Door Test			
		Target	Measured
CFM@50	3 ACH50	2275.30 CFM50	908.3 CFM50
ACH@50		3 ACH50	1.20 ACH50
House to Garage	Connection	45 Pa	45 Pa

Job ID: 113917

10226 Hartwood Dr

Duilding Chall (Dlawer Dage	·Took		
Building Shell/Blower Dooi	lest		
		Target	Measured
CFM@50	3 ACH50	2275.30 CFM50	908.3 CFM50
ACH@50		3 ACH50	1.20 ACH50
House to Garage Connection		45 Pa	45 Pa
Building Shell/Insulation (In	sulation installed to manufacturer's specs/C	Grade 1)	
Exterior Walls	Insulation Type		R-Value
Walls	B6 - Open Celled Foam - R3.7 per inch		20
Rim/Box	B6 - Open Celled Foam - R3.7 per inch		19
Ceiling	Insulation Type		R-Value
Blown attic	B6 - Open Celled Foam - R3.7 per inch		38
Floor Systems	Insulation Type		R-Value
Floors	B6 - Open Celled Foam - R3.7 per inch		30
Foundation	Insulation Type		R-Value
Foundation	B4 - Fiberglass Blanket Vinyl		19
Building Shell/Windows			
		U Value	SHGC
Above grade windows		.30	.36
Foundation windows		.29	.23
Above grade slider		.28	.40

Job ID: 113917

10226 Hartwood Dr

Whole House Mech Ventilation

Target Measured

Job ID: 113917

Flow volume 87 CFM 89 CFM

Mechanical System #1 Furnace - Conditioned Area

Rough Duct Testing Results

Furnace Carrier - 59TP6C080V211120

Test Condition Rough In With Air Handler - 2021 IECC R403.3.6 #3

AC Coil Carrier - CVAVA4821XMAE

Manual JDS used

Conditioned floor area 4160

Calculated for 6 CFM/100SF

Max duct leakage allowed 249

Testing result 152

Duct Location Supply % Return %

Conditioned Space 100 100



10226 Hartwood Dr

Mechanical System #1 Furnace - Conditioned Area			
Item	Design	As Built	
Cooling season design temperatures used in loads are within defined ENERGY STAR limits	90	90	
Heating season design temperatures used in loads are within defined ENERGY STAR limits	0	0	
HVAC design home orientation matches rated home AND sensible, latent, and total DESIGN heat gains are documented for the correct orientation	E	E	
Number of occupants used in loads is withing +/- 2 of home to be certified	5	6	
Conditioned Floor Area used in HVAC design is between 100sqft less than and 300sqft greater than the home being certified	4437.6	4160	
Window area used in HVAC design loads is between 15sqft less than and 60sqft larger than home being certified, or, for homes with > 500 sq ft of window area, between 3% smaller and 12% larger	338	318	
Predominant window SHGC used in loads is within 0.1 of predominant value of home to be certified	.36	.36	
HVAC DESIGN REPORT FOR MODELS: variations in total heat gain			

Item	Design	As Built
Furnace manufacturer and model number on installed equipment matches HVAC Design report	59TP6C080V211120	59TP6C080V211120
A/C Coil manufacturer and model number on installed equipment matches HVAC Design report	CVAVA4821XMAE	CVAVA4821XMAE
A/C Condenser manufacturer and model number on installed equipment matches HVAC Design report	GA4SAN54800NABAA	GA4SAN54800NABAA

18.2 24.1

113 | 130

Job ID: 113917

across orientations is = or < 6kBtuh on Design Report

limit (4.15) selected by HVAC designer

HVAC DESIGN REPORT: Cooling size % (4.13) is within the cooling sizing