


## Reroofing Precautions

Reroofing your home *may* adversely affect VENTILATION of ANY GAS APPLIANCE causing hazardous gases to stay in the home. ***IF*** the FLUE CAP is replaced or the ventilation pipes are altered a hazardous condition ***may be*** created. Check with your contractor to ensure that the vents operate properly or CONTACT A LICENSED HEATING CONTRACTOR. IT IS ALSO RECOMMENDED THAT A CARBON MONOXIDE DETECTOR BE PURCHASED AND INSTALLED AS PER THE MANUFACTURER'S SPECIFICATIONS.



PIKES PEAK REGIONAL BUILDING DEPARTMENT  
2880 International Circle  
327-2880  
[www.pprbd.org](http://www.pprbd.org)