Pikes Peak REGIONAL Building Department

PPRBD Conveyance Inspections & Fees

Fees are applicable per Appendix B, Table E of the Pikes Peak Regional Building Code, 2023 Edition

Conveyance Certificate to Operate / Temporary Certificate to Operate

 Certificates to Operate and Temporary Certificates to Operate may be issued following any of the following inspections with the exception of a HO5.

H01 – Periodic Inspection

This inspection is an overall compliance inspection of the conveyance. If no violations are
noted in the inspection report, a six-month Certificate to Operate (CO) will be issued expiring
the last day of the next scheduled inspection month. If violations are noted in the inspection
report, a Temporary Certificate to Operate (TCO) may be issued. The TCO, if issued, will
have an expiration date based on the severity of the violation at which point a Re-Inspection/
Resolution (HO3) will be performed to either verify corrections to noted violations or proceed
with shutdown of the conveyance.

Туре:	H01
Elevator	\$177.00
Escalator	\$355.00
Platform Lift (VPL)	\$177.00
Dumbwaiter	\$50.00

• HO1 inspection fees are applicable based on conveyance type:

H02 – Six Month Inspection

- This inspection addresses ongoing compliance ensuring no issues with the operation of the conveyance have evolved. If no violations are noted in the inspection report a six-month Certificate to Operate (CO) will be issued expiring on the last day of the next scheduled inspection month. If violations are noted in the inspection report, a Temporary Certificate to Operate (TCO) may be issued. The TCO, if issued, will have an expiration date based on the severity of the violation at which point a Re-Inspection/Resolution (HO3) will be performed to either verify corrections to noted violations or proceed with shutdown of the conveyance.
- HO2 inspections may not require a physical inspection and are conducted at no additional cost.

Pikes Peak REGIONAL Building Department

PPRBD Conveyance Inspections & Fees (continued)

Fees are applicable per Appendix B, Table E of the Pikes Peak Regional Building Code, 2023 Edition

H03 – Re-Inspection / Resolution

- This inspection pertains to violations that have been noted in previous inspection reports. An inspector will either make a site visit or may utilize electronic means (video, pictures, email documentation) to verify previous violations have been corrected.
- Each HO3 inspection generates a \$50.00 fee.

<u> H05 – Red Tag</u>

- This is an inspection result for a conveyance that has been shut down either by request of the building owner or from ongoing code violations that have not been resolved. A conveyance may not be returned to service until all code violations are resolved and the fees associated with that conveyance are paid in full.
- All HO5 inspections will generate a \$200.00 fee.
- *Exception:* Elevators, escalators, and lifts that are in an existing H05 status will not be charged this fee.

<u>H06 – Elevator Witness Test</u>

- A Witness Test is an inspection that is conducted with a licensed elevator mechanic present.
 H06 Witness Tests are applicable to all types of Elevators and Platform Lifts (VPL).
- These inspections will be billed at \$50.00 per hour.
- Dumbwaiters are exempt from Witness Test inspections.

<u>H07 – Escalator Witness Test</u>

- A Witness Test is an inspection that is conducted with a licensed elevator mechanic present.
 H07 Witness Tests are applicable to all types of Escalators and Moving Walks.
- Billing for HO7 inspections is included in the applicable HO1 fee .