



Jesik Consulting
Geotechnical, Water, Testing

102-D Oneida Street
Pueblo, Colorado 81004
(719) 582-5588
www.jesik.us

June 12, 2018

Jim Matthews
Sherlock Holmes
9 Ridge Road
Colorado Springs, CO 80904
jimjmatthews@msn.com

RE: Open Excavation Observation
For 24830 Impala Circle
Calhan
El Paso County, Colorado

Project No: 17-7351-8

Dear Mr. Matthews,

Jesik Consulting observed the foundation excavation on 6-11-18. The soils observed generally consisted of brown SAND with coarse gravel to a depth of approximately 2 feet. The soils observed are consistent with the soils reported in the Jesik Consulting Project No. 17-7351-8, dated 5-2-18. The foundation type and bearing capacity as shown in the report is appropriate for this project.

Sincerely,



Joseph A. Jesik, P.E.
Chief Engineer